

TRUCK ID SHEET

FILE # GR10016

LOCATION: St. Charles, MO

UNIT : 1989 International S1700 Navstar (1754)

VIN#: 1HTLCCFP7KH644192

MILEAGE: 502,885

INTER. COND: Poor

PAINT COND.: Poor

TYPE: Dump Truck

SEATS: Manual Bench

ENGINE: INT DT360

OIL LEVEL: Good

COOLANT LEVEL: Good

TRANSMISSION: 5 - speed

REAR AXLE : 2 - speed

FRAME: Steel

FUEL TANKS: 2 - 50 gal. steel

SUSPENSION: 12,000 / 21,000

STEERING: Power

BRAKES: HydroVac

REAR SUSPENSION: 21,000 Spring

FRONT WHEELS: Steel

REAR WHEELS: Steel

TIRE	SIZE	/32	RECAP YES/NO	DAMAGE YES/NO	TIRE	SIZE	/32	RECAP YES/NO	DAMAGE YES/NO
------	------	-----	-----------------	------------------	------	------	-----	-----------------	------------------

LF	22.5	8/		x		x	RF	22.5	8/		x		x
LRFO	22.5	10/		x		x	RRFO	22.5	10/		x	x	
LRFI	22.5	8/		x		x	RRFI	22.5	8/		x		x

REMARKS: 10' Dump Bed / Engine runs great / Clean title